

Oil Field Environmental Incident Summary

Incident: 20140116160124 **Date/Time of Notice:** 01/16/2014 15:52

Responsible Party: Continental Resources, Inc.

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: MPHU CTB

Field Name:

Well File #:

Date Incident: 1/16/2014 **Time Incident:** 11:38 **Facility ID Number:** 404538-02

County: BOWMAN **Twp:** 130 **Rng:** 104 **Sec:** 22 **Qtr:**

Location Description: Lightly misted area to the east/south-east, approx. 0.4 acres

Submitted By: Stacy Aguirre

Received By:

Contact Person: Stacy Aguirre
PO Box 268870
Oklahoma City, OK 73126

General Land Use: Cultivated

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0.25	barrels	0.25	barrels	0.25	barrels
Brine	0	barrels	0	barrels		
Other	0	barrels	0	barrels		

Description of Other Released Contaminant:

Inspected: **Written Report Received:** 12/29/2016 **Clean Up Concluded:** 1/17/2014

Risk Evaluation:

none

Areal Extent:

Approx. 0.4 acres to the east/south-east

Potential Environmental Impacts:

topsoil

Action Taken or Planned:

Lightly misted area off location will be dragged and peat moss will be applied where necessary.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 1/21/2014 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release sprayed off location. Followup is necessary.

Date: 1/23/2014 **Status:** Inspection

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

1/23/14 - 13:30 on location. Photos with GPS. Location given in report incorrect. Location of the CTB is 130-106-13CCC. Impact area extends from 13CCC across county road into 24BB. Impact area appears to be greater than the 0.4 acres reported. Vegetation has been removed from spray area, but very visible staining remains. Work plan and soil samples will be necessary. Impact area is in agricultural fields.

Date: 4/22/2014 **Status:** Inspection

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

The weather was 56 °F, with wind from the southeast 20 miles per hour. I can still see misted area in the field on the north side and south side. The grass in the ditch is growing, and some weeds are growing in the field next to flare. No evidence of misting on the gravel road. No soil removed from the fields; it may be best left in place. Further followup in mid-summer is needed.

Date: 10/7/2014 **Status:** Inspection

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location at 10/7/14.

No sign of spill at the described location. Remediation is complete. There have been several incidents at this location in the last year. Followup with company is necessary to ensure that spill countermeasures are in place and being followed.

Date: 3/9/2016 **Status:** Correspondence

Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Bill Suess sent a No Further Action letter dated March 9, 2016.